

10/796110

COFC

Docket No.: M4065.1020/P1020

(PATENT)

## IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Letters Patent of:

Larry D. Kinsman

Patent No.: 6,979,902

Issued: December 27, 2005

For: CHIP SIZE IMAGE SENSOR CAMERA

MODULE

Certificate

FEB 1 3 2006

of Correction

## REQUEST FOR CERTIFICATE OF CORRECTION PURSUANT TO 37 CFR 1.322

Attention: Certificate of Correction Branch Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Dear Sir:

Upon reviewing the above-identified patent, Patentee noted an error which should be corrected.

In Claim 45, the PTO made the following error to be corrected:

Column 8, lines 49-50, "surface near the top of the substrate." should read -- surface.--.

The error was not in the application as filed or amended by Applicant; accordingly no fee is required.

Patent No.: 6,979,902 Docket No.: M4065.1020/P1020

Transmitted herewith is a proposed Certificate of Correction effecting such amendment. Patentee respectfully solicits the granting of the requested Certificate of Correction.

By\_\_

Dated: February 7, 2006

Respectfully submitted,

Thomas J. D'Amico

Registration No.: 28,371

DICKSTEIN SHAPIRO MORIN &

OSHINSKY LLP

2101 L Street NW

Washington, DC 20037-1526

(202) 785-9700

Attorneys for Applicant

PTO/SB/44 (04-05)
Approved for use through 04/30/2007. OMB 0651-0033
U.S. Patent and Trademark Office: U.S. DEPARTMENT OF COMMERCE

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. (Also Form PTO-1050)

## UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page \_1\_ of \_1\_

PATENT NO.

6,979,902

APPLICATION NO. :

10/796,110

ISSUE DATE

December 27, 2005

**INVENTOR** 

Larry D. Kinsman

It is certified that an error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In Claim 45, the following error is corrected:

Column 8, lines 49-50, "surface near the top of the substrate." should read --surface.--.

MAILING ADDRESS OF SENDER (Please do not use customer number below): Thomas J. D'Amico DICKSTEIN SHAPIRO MORIN & OSHINSKY LLP 1 2101 L Street NW Washington, DC 20037-1526